


MiNi implant system at the mandibular incisors

Dr. Kwang Bum Park

Case by. Dr. Kwang Bum Park

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved




A male patient presented with discomfort of the mandibular incisors. Intraoral images revealed that the two central incisors had apical lesions and mobility. While the two lateral incisors were quite solid, they were super-erupted, making them a threat to the upper incisors. The treatment plan was to extract all four teeth and place two MiNi implants in the position of the lateral incisors.

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved






To deal with the excessive alveolar bone and gingiva after implant placement, a scalloping incision was made around the incisors. After extraction and flap opening, the alveolar crest was trimmed down to the level of the adjacent teeth.

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.


Copyright
All rights reserved

Case by. Dr. Kwang Bum Park






Two 3.0 MiNi fixtures were placed in the sockets of lateral incisors




Two EZ posts were connected to the fixtures



COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved



The excessive post lengths were trimmed using a high-speed bur. A temporary bridge was made chair-side and delivered. When compared with the original position, the incisal level of the anterior teeth was much better.

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved


Case by. Dr. Kwang Bum Park



Panoramic scan after surgery

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.


Copyright
All rights reserved



Intraoral scans taken at different stages of the procedure: two months after placement, with impression copings in place, and the delivery of the zirconia customized abutment. (in progress)

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved



140320 - Panoramic scan at 1 year follow-up



Intraoral & panoramic scans at 5 years follow-up

COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved



COPYRIGHT(C) MEGA'GEN IMPLANT CO.,LTD. ALL RIGHTS RESERVED
No part of this publication may be reproduced, distributed, or transmitted in any form or by any means, including photocopying, recording, or other electronic or mechanical methods, without the prior written permission of the publisher, except in the case of brief quotations embodied in critical reviews and certain other noncommercial uses permitted by copyright law.

Copyright
All rights reserved