


**Replacement of fractured
central incisor (#11)
with immediate implant
& Root Membrane Technique**

Dr. Miltiadis Mitsias


Case by. Dr. Miltiadis Mitsias

Case by. Dr. Miltiadis Mitsias




Initial panoramic radiograph

Case by. Dr. Miltiadis Mitsias



Computed tomography evaluation
Initial clinical view of fractured tooth
Tooth has horizontal fracture
Immediate implant placement with Root Membrane Technique



Temporary abutment placed immediately after implant placement

Immediate provisional restoration

Periapical radiograph after immediate implant placement & delivery of provisional restoration

Cone beam computed tomography at placement

Case by. Dr. Miltiadis Mitsias



Final restoration after cementation
Occlusal-buccal view immediately after delivery of final restoration
Peri-apical radiograph taken 8 years after implant placement
8-year follow-up clinical view

